

March 17, 2010

1

SUBJECT 1699A

OUTLINE OF INVESTIGATION

FOR

OUTLET BRANCH CIRCUIT ARC-FAULT CIRCUIT-INTERRUPTERS

Issue Number 2

MARCH 17, 2010

COPYRIGHT © 2010 UNDERWRITERS LABORATORIES INC.

No Text on This Page

CONTENTS

INTRODUCTION

1 Scope	4
2 Glossary	4
3 Components	4
4 Units of Measurement	5
5 Undated References	5

CONSTRUCTION

6 General	5
7 Spacings	5
8 Terminals	5
9 Housings	6
10 Grounding	6

PERFORMANCE

11 General	6
12 Impact Test	7
13 Leakage Current Measurement	7
14 Arc Fault Detection Tests	7
14.1 Carbonized path arc ignition test	7
14.2 Carbonized path arc clearing time test	7
15 Unwanted Tripping Tests	8
15.1 Loading condition II – normal operation arcing	8
16 Operation Inhibition Tests	8
16.1 General	8
16.2 EMI filter	8
17 Short Circuit Current Test	8

RATINGS

18 General	9
------------------	---

MARKINGS

19 General	9
20 Installation Instructions/Owner's Manual	9